## ARIZONA CORPORATION COMMISSION - PIPELINE SAFETY GROUP ANNUAL INSPECTION REPORT - Gas System Operators

Inspection Dat	<b>Date :</b> 10/17/2018					Last	Inspection Date :	10/26/2017		
Name of Facili	ty: EASTSI	DE COVE	NANT CHU	JRCH		OPID #:	33837	Phone: (520) 8	85-3192	
Cell Phone:         Fax: (520) 885-3054         Email: taylor@ecctucson.org										
Address of Fa	cility: 551 N	N CAMINO	SECO				City:	TUCSON		
State: AZ				<b>Zip:</b> 85710 <b>Contact</b>			Contact Person	n: Taylor Burgoyne		
Operator Name: EASTSIDE COVENANT CHURCH Phone: (520) 885-3192										
Operator Address: 551 CAMINO SECO City: TUCSON								TUCSON		
[x] please check box if this is to be the mailing address										
State: AZ Zip: 85710 Number of Buildings: 4										
Facility Type:	Church / Car	mp / Scho		Priority: 1				Gas Supplier: Southwest Gas		
LPG: No		Natural:	Yes	Number	of Meters:	One	Operat	ing Pressure: 7"	WC	
GAS SYSTEM	GAS SYSTEM HISTORY  A. Piping Type: Steel  Date Installed:									
1. Has a written operation and maintenance plan been established meeting the requirements of the regulations and review records maintained?									UnSatisfactory	
2. Has a written emergency plan been established and does operating personnel have knowledge of emergency procedures and are records maintained?									UnSatisfactory	
3. Has a map of the gas system been developed showing meter and valve locations, mains, and service lines?									Satisfactory	
4. Are operation and maintenance personnel qualified and are OQ records maintained?									UnSatisfactory	
5. Has all above ground pipe been maintained?									UnSatisfactory	
6. Has cathodic protection been tested at proper intervals and records maintained? Does it meet the negative voltage of at least 0.85 volt?									Satisfactory	
7. Have required valves been checked and serviced at intervals not exceeding 15 months but at least once each calendar year and records maintained?									UnSatisfactory	
8. Have periodic odorization checks been conducted and records maintained?									UnSatisfactory	
<b>9.</b> Has a leak survey of the system been conducted at intervals not exceeding 15 months but at least once each calendar year and records maintained?									UnSatisfactory	
10. Has operator filed annual report?									Satisfactory	
Last year on F	ile: 2016	6								
The annual report for year 2017 was received on site.										
		Total	Violations I	Found:		7				
<b>NOTE:</b> Items listed or marked <i>Unsatisfactory</i> or <i>Not Checked</i> shall be corrected no later than 30-days following the receipt of this report. Correspondence regarding violations can be emailed to safety@azcc.gov or mailed to Pipeline Safety Section, 1300 W. Washington Street, Phoenix, AZ 85007. Failure to comply will result in this matter being forwarded to our Legal Council for further action, and this action may result in termination of gas service to your facility.										
The findings of this	report are ba	ased on ol	oservation r	nade and docur	mentation a	vailable to insp	pectors at the time	of inspection.		
Operator Representative	cathy wysop	oal				ACC Represe	Luis Guzi	man		

